




























































Obsolete DRILLS



























CODE	ALTERNATIVE PRODUCT	DIFFERENCE(S)
A001	A002 	 --> 
A030	A130 	
A034	A134 	
A035	A350 	
A036	A530 	
A090	A095 	 --> 
A091	A096 	 --> 
A095		
A098		
A099		
A109		
A112		
A114		
A128		
A129		
A131		
A146	A951/A952 	
A189		
A190		
A191		
A194		
A199		
A226		
A340	A345 	
A403		
A404	A401 	
A500	A002 	 -->  S.P.
A504	A553/A554 	 DIN 6535 HE  DIN 6535 HA
A505	A553/A554 	 DIN 6535 HE  DIN 6535 HA
A507	A577 	 --> 
A511		
A512	A554 	 --> 
A515	A551 	

			TiN HSS --> TiAIN HSCo
A521	A552		TiN --> TiAIN
A522			
A524	A551		TiN --> TiAIN
A525			
A567	A577		TiCN --> TiAIN
A587	A597		TiCN --> TiAIN
A621	A002		ST --> TiN
A700	A777		S.P. --> DIN 338 135°
A918	A916		HSS --> HSCo
R100	R002		
R120	R022		
R400			
R402			
R512	R510		TiAIN --> TiN
R522	R520		TiAIN --> TiN
R550	R558		TiN --> TiAIN
R552	R558		
R555	R553		TiN --> TiAIN
R556	R557		TiN --> TiAIN




























Obsolete CUTTERS






























CODE	ALTERNATIVE PRODUCT	DIFFERENCE(S)
C102	C123 	HSCo → HSCo XP
C106	C126 	HSCo TiCN → HSCo XP Super R
C131	C192 	HSCo DIN 844 K → HSS XS1 BS 122/4
C134	C192 	HSCo → HSS XS1
C136	C139 	HSCo TiCN → HSCo XP Super R
C137	C191 	HSCo TiCN DIN 327 H → HSS XS1 Bronze BS 122/4
C145	NONE	
C200	C247 	HSCo → HSCo XP
C202	C273 	HSCo → HSCo XP
C204	C246 	HSCo TiCN → HSCo XP Super R
C250	C291 	HSCo DIN 844 K → HSS XS1 Bronze BS 122/4
C255	C292 	HSCo → HSS XS1
C290	C295 	HSCo TiCN → HSCo XP Super R
C297	C291 	HSCo TiCN DIN 844 K → HSS XS1 Bronze BS 122/4
C303	C305 	HSCo → HSCo XP
C304	C306 	HSCo → HSCo XP
C324	C324 	Super R → Super G
C326	C353 	HSCo TiCN → HSCo XP Super G
C333	C333 	HSCo → HSCo XP
C336	C336 	HSCo → HSCo XP
C348	C352 	HSCo TiCN → HSCo XP Super G
C358	C358 	HSCo TiCN → HSCo XP Super G
C359	C359 	HSCo TiCN → HSCo XP Super G





























C367	C367		
C381	C381		
C383	C383		
C388	C388		
C402	C407		HSCo NR → HSCo XP NRA
C414	C908		HSCo TiCN NR → HSCo XP Super G NRA
C426	C426		
C428	C428		
C442	C400		
C448	C493		HSCo NR → HSCo XP NRA
C449	C404		
C458	C414		
C465	C403		
C478	C477		NF → NR
C480	C475		NF → NR
C492	C492		
C515	C516		DIN 1889 L → DIN 844 K
C550	C530		HSCo DIN 327 H → HSS BS 122/4
C904	C921		→ Super G
C906	C270		HSCo XP → HSCo
C907	C907		
C908	C908		
C920	C920		
C921	C921		
C922	C922		
C974	C291		HSS → HSS XS1









Obsolete TAPS

CODE	ALTERNATIVE PRODUCT	DIFFERENCE(S)
E115		no Ø 3/32"
E170	E214 	HSS XR --> HSCo
E171	E265 	HSS XR --> HSCo
E172	E208 	HSS XR --> HSCo
E173	E259 	HSS XR --> HSCo
E174	E207 	HSS XR --> HSCo
E175	E258 	HSS XR --> HSCo
E281	E531 	HSCo ISO 529 --> HSS DIN 2183
E304		
E311	E309 	
E312	E317 	
E318	E302 	
E319	E302 	
E328	E305 	
E329	E306 	
E338	E306 	
E339	E313 	
E368	E310 	
E369	E309 	
E370	E462 	HSCo --> HSCo XP TiAIN
E371	E463 	HSCo --> HSCo XP TiAIN
E372		
E375		no M5
E376		no M18
E418	E403 	Hard-lube 40° --> Super B 45°
E419	E403 	Hard-lube 40° --> Super B 45°
E438	E308 	
E439	E308 	
E456	E403 	TiCN 40° --> Super B 45°
E457	E403 	TiCN 40° --> Super B 45°
E458	E301	
E459	E301	
E460		no M5
E461		no M18

E462			no M5
E463			no M18
E496	E402		
E497	E402		
E535			
E541			
E548	E042-E043		
E549	E040-E041		
E554	E096		
E561	E091		
E563	E099		
E565	E090		
E593	E097		
E594	E098		
E595	E080		
E598			
E622			
E623			
E750	E550		ISO 2284
E751	E710		ANSI
E801	E513		CS  HSS ISO 529
E807	E547		CS ISO 5969 HSS ISO 2284
E919	E050		
E920	E049		
E921	E050		
E922	E049		
E923	E982		Hard-lube 
E924	E052		
E925			
E926			
E927	E054		
E928	E057		
E929	E058		
E930	E053		

E931	E059		
E932			
E933			
E934			
E935			
E941	E020		
E942	E030		
E944	E022		
E945	E032		
E946	E044		
E949	E045		
E950	E055		
E951	E060		
E952	E047		
E953	E056		
E954	E095		
E955	E000		
E958	E002		
E959	E022		
E964	E000		
E967	E002		
E968	E022		
E976			
E979			
E982	E048		
E983	E011		
E984	E013		
E985	E010		
E986	E012		
E988	E042		
E990	E043		
E992	E042		
E994	E042		
E995	E046		
E996	E982		

			   
<b>E998</b>	<b>E051</b>		

© Sandvik AB

Latest update: 14/12/2006 10.12.19

[Comment this page](#)



Obsolete DIES

CODE	ALTERNATIVE PRODUCT	DIFFERENCE(S)
F322	F320 - F120	
F332	F330 - F130	
F342	F340 - F140	
F352	F350 - F150	
F372	F370 - F170	
F390	F180	
F510	F110	
F570	F170	<div style="border: 1px solid black; padding: 2px; display: inline-block;"><b>HSS</b></div>



**Obsolete REAMERS**

CODE	ALTERNATIVE PRODUCT	DIFFERENCE(S)
B110		
B120	B121 	
B245		
B246		
B501	B156 	ST
B502	B157 	ST



**Obsolete MISCELLANEOUS**

CODE	ALTERNATIVE PRODUCT	DIFFERENCE(S)
G131		
M100		
M101		
M153		
M154		
M156		
M158		